

SAFE HOME / LEADSAFE CHARLOTTE

CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERVICES

BID OPENING CERTIFICATION RECORD

Public Body Estimate

Address	PBE Amount	PBE - 15%	+1 5%
2400 RINGWOOD (08)	\$18,075	#20,786 ²⁵	15,363.25
3326 ROGERS (09)	#9250	#10,637,50	# 7,86250
3833 BLANDWOOD (10)	\$40,591	# 46,679.65	\$ 34,502.35
			,

Bid Results							
Addresses	Bidder 1	Bidder 2	Bidder 3	Bidder 4	Bidder 5		
	SCHULTZ	JASPER	J.P.GROUP	YESHUAS	ICM		
2400 RINGWOOD(08)	\$ 25,200.00	\$26,175.00	#23,900,00	\$20,800. XX	727,344.00		
	\$ 5,030.00	#6775,00	No Biogn	\$8,800,20	No BIDOM		
3833 BLANDWOOD (10)	\$46,825.00	#46,980.00	47,975.	#39,900,000 xx	# 47,850.00		
Bid Walk Attendees							

JASPER BIO DENING.

J.P.GROUP

VESHUAS BIO DENING.

ICM

This is to	certify that bids for the job identified above were publicly opened and read aloud in the Neighborhood & Business Services
Office lo	cated at 600 E. Trade Street, Charlotte, NC.
Bids Ope	ened By: MILL AN LON Mentally Bids Recorded By: J.M. MAILON - Mohorn ened By: Date: SEPTEMBER 06, 1018 gm
	5-20 0-20 01 10/01/
Witness	ed By: Date: Dete: Dete
	•
Note:	Responsive bids are those which fall within a range of 15% above and 15% below the public body cost estimate. As a
	general rule, the lowest responsive bid is recommended to the property owner for consideration.



SAFE HOME
CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Invitation to Bid

HN319-8

Documents included in Package:

- 1) Instruction to Bidders
- 2) Specs by Location/Trade (Scope of Work)
- 3) Subcontractor Certifications (if applicable)
- 4) Floor Plan / Site Drawing (if applicable)

Bid Walk & Bid Opening:

Project Address:	2400 Ringwood Street	SAFE HOME CHARLOTTE LEADSAFE CHARLOTTE
Bid Walk:	08/30/18 at 10:00 am (THU	RSDAY)
Bid Opening:	09/06/18 at 2:00 pm (THUF	RSDAY)
Client Name:		Contact Number:
Project Manager:	James Mahon	Contact Number: 704-614-6655

Bid Walk and Bidding Instructions:

All bid walks are mandatory.

If you are going to be late the policy is the following:

Contact me BEFORE the start time if you are going to be late. If you are going to be more than 10 minutes late, we will proceed without you and you will not be permitted to bid.

The day of a bid walk the best way to reach me is at _James Mahon (cell # 704-614-6655).

Bids must be received by the date, time and place specified. All others will be considered non responsive and disqualified.

The Bids will be opened at 600 East Trade St. immediately following the above due date and time.



SAFE HOME

CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Company Acknowledgement:

The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at 2400 Ringwood Street to be funded through the City of Charlotte Neighborhood & Business Services, in addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money:

the advised respective contractual, for the sum of money:

All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications:

Written total

Specs Dated: AUGUST 22,2018 Number of Pages: 3- REHAB + 3 LbP

Addenda # 1 Dated: Number of Pages:

Addenda # 2 Dated: Number of Pages:

Project Schedule: Minimum Start Date - 4 weeks after Bid Due Date

Completion Deadline: OCTOBER 31, 2018

Please Print and Sign:	
Company Name/Firm:	ESHUA'S Builders LLC
Authorized Representative	Name: John J. Lyons, SR
Signature:	Mart Date: 9-6-18



SAFE HOME

CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Requirements For Bidders

The City awards rehabilitation bids to the lowest responsive and responsible bidder. A responsible bidder for the safe home program is one who:

- 1) Is a licensed general contractor in the State of North Carolina;
- 2) Has an Renovate, Repair & Paint Certification (http://www2.epa.gov/lead/renovation-repair-and-painting-program);
- 3) Is not listed on a local, state or federal debarment list;
- 4) Carries an appropriate amounts of insurance;
- 5) Can provide references verifying the contractor has completed work of a similar scope in a good workmanship like manner or successfully completed prior work for the Safe Home program. Referenced work must have been completed in one year or less from date of this invitation to bid.

A responsive bidder must:

- 1) Submit all requested documentation on time;
- 2) Meet the above requirements for responsibility at the time of bid submittal;
- 3) Have the capacity to meet the required schedule for the project.
- 4) Existing rehab projects contracted by the contractor must be on schedule.

The City reserves the right to waive any minor informalities or irregularities, which do not go to the heart of the bid submittal or prejudice other offers, or to reject, for good and compelling reasons, any or all bid submittals.

James Mahon Rehabilitation Specialist City of Charlotte Neighborhood and Business Services 600 E. Trade St. Charlotte, NC 29202

PH: (704) 432-2321 Fax: (704) 336-3489

NEIGHBORHOOD & BUSINESS SERVICES

http://housing.charlottenc.gov | 600 E. Trade Street | Charlotte, NC

Work Specification

Prepared By: City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

Work Specification - City of Charlotte Housing & Neighborhood Services

	Property Details								
	Address:	2400 Ringwood St	1	Owner:	Darr	/l Williams			
		Charlotte, NC 28208		Owner Phone:	(917) 658-1437				
	Structure Type:	Single Unit		Program(s):	Emergency Repair				
	Square Feet:	1680			Tested- HAS LEAD LeadSafe 2016 Healthy Homes LBF SH FY18 Not Ranke		AD		
	Year Bullt:	1956						6	
	Property Value:	86900					nked		
	Tax Parcel:	07106114							
	Census Tract:								
	Property Zone:	Council District 3							
	Repairs								
\bigcirc	Description	•			Floor	Room		<u>Exterior</u>	
رد	Emergency Heating U	Init Replacement							
						1		11.	
			Bid Cost:		_x		=	NA	
				Base		Quantity		Total Cost	
2	Doorbell System					GEN REC	a C		
<u>U</u>	Install a doorbell system containing a low voltage transformer, power connection, buzzer and front door button.								
			Bid Cost	Annual Control of the	х		=	400-	
				Base		Quantity		Total Cost	
5	Permits Required					GEN REC	ຊ		
<u>پ</u>	•	nsible obtaining and paying for all perm	nits required	. Said permits s	hall ind	dude all iten	ns in this	s scope of work.	
			Rid Cost	*	X	1	=	570-	
			Dig 0030	Base		Quantity		Total Cost	
	Dumpster					GEN REG	5		
(4)	After procuring all requi	ired permits, place AS MANY roll-off du ol methods. Remove dumpster and rep trallers.	ımpsters as alr any evide	needed withou ence of the dun	t dama npsters	ging the site	. Collec	t construction y haul debris	
			Bid Cost		X	Bertelenson	=	500-	
			Dia Gost	Base		Quantity		Total Cost	

8/22/2018

Response Due: 9/6/2018 2:00 PM


Work Specification

	WOIN OPCOMICATION						
3	Portable Toilet				GEN RE	Q	
מ	Provide temporary tollet facilities from job start until approval	of permanent fac	cilities.				
		Bld Cost:		Х	1	=	300
		Bid Cost	Base		Quantity		Total Cost
\hat{a}	Smoke Detector Hard Wired				GEN RE	Q	
9	Install UL approved, interconnected, ceiling mounted smoke	and heat detecto	rs permane	ntly wi	red into a re	ecepta	cle boxes with
	battery backups in bedrooms and outside of sleeping areas.		·	•			
		Bid Cost:		X	l	=	1500
		<u> </u>	Base		Quantity		Total Cost
\widehat{A}	Combination CO / Smoke Detector Hard Wired				GEN RE	EQ.	
\mathcal{D}	Install a hard wired combination carbon monoxide and smok	e detector with b	attery back	up.			
		Bid Cost:		X	(=	180-
		Bia Cost	Base		Quantity		Total Cost
2)	Electric Complex 200 AME				GEN RE	ΞQ	
8	Electric Service 200 AMP	at 440/220 voit	24 alreadt na	anel ho	GEN RE		weather head.
8	Replace electrical service with new 200 amp, main disconne	oct, 110/220 volt, of all sub-panels.	24 circult pa Caulk exte	anel bo	ard, meter	socket	, weather head,
8		oct, 110/220 volt, of all sub-panels.	24 circult pa Caulk exte	rlor sei	ard, meter	socket	, weather head,
8	Replace electrical service with new 200 amp, main disconne	ct, 110/220 volt, of all sub-panels. Bid Cost: _	Caulk exte	anel bo rlor sei	eard, meter vice penetr	socket	2500
8	Replace electrical service with new 200 amp, main disconne	of all sub-panels.	Caulk exte	rlor sei	ard, meter	socket	a, weather head, 2500 Total Cost
8	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement	of all sub-panels.	Caulk exte	rlor sei	eard, meter vice penetr	socket ration.	2500
9	Replace electrical service with new 200 amp, main disconne	of all sub-panels. Bid Cost: _	Base	rlor sei	ard, meter vice penetr / Quantity GEN RI	socket ration.	2500 Total Cost
9	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable cable. Include replacement of the service cable cable cable cable cable cable cable cable cable. Include replacement of the service cable	of all sub-panels. Bid Cost: _	Base	rlor sei	ard, meter vice penetr / Quantity GEN RI	socket ration. = EQ s, This	2500 Total Cost
(B)	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable cable. Include replacement of the service cable cable cable cable cable cable cable cable cable. Include replacement of the service cable	of all sub-panels. Bid Cost: _	Base	rlor sei	ard, meter vice penetr / Quantity GEN RI	socket ration.	2500 Total Cost
9	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable cable. Include replacement of the service cable cable cable cable cable cable cable cable cable. Include replacement of the service cable	of all sub-panels. Bid Cost: _	Base Use code a	rlor sei	GEN RI	socket ration.	2500 Total Cost s also includes any
9	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and gr	of all sub-panels. Bid Cost: _ out entire house. Bid Cost: _	Base Use code a	ppropix_	GEN RI Quantity GEN RI Quantity GEN Ri able building	EQ s, This	7500 Total Cost s also includes any Total Cost s. Building permits
(8)	Replace electrical service with new 200 amp, main disconne service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and cable. Include replacement of the service cable, ground rods and Plates Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throughout wall or ceiling damage repairs. See Attached Lead Scope All work shall be performed in accordance with applicable rewill be obtained as appropriate. Mecklenburg County requires	of all sub-panels. Bid Cost: _ out entire house. Bid Cost: _	Base Use code a	ppropix_	GEN RI Quantity GEN RI Quantity GEN Ri able building	EQ s, This	Total Cost Salso includes any Total Cost S. Building permits

8/22/2018 2

Work Specification

	Work opcomoduon								
$\widehat{\mathbb{Q}}$	Vinyl Window				EXTERI	OR	Exterior		
حال	Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW- E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. (17)								
		Bid Cost:		X	1	=	73577		
		<u></u>	Base		Quantity		Total Cost		
(2	Prehung Metal Door Entrance				EXTERI	OR	Exterior		
	Remove existing door, frame and threshold, Install new Energy dead bolt and lever handled door hardware keyed alike. Install Apply primer and topcoat. This installation to include repairing a floor joists and sill.	wide peep sigh	t. New cas	ing and	d shoe mold	ling wil	l match existing.		
		Bid Cost:	b	x)	=	550		
			Base		Quantity		Total Cost		
13)	Repoint Masonry Bricks				EXTERI	OR	Exterior		
	Rake out existing mortar joints to a minimum depth of 1/2". Co	mpletely fill mo	rtar joints t	o mato	h existing.				
		Bid Cost:	~	X	1	=	200		
			Base		Quantity		Total Cost		
	Certification								
	Contractor Name: ESHUA Buil	glers L	10		Total G	ost:	20,800		



LEAD ABATEMENT SCOPE OF WORK

& INSTRUCTIONS TO BIDDERS

Address

2400 Ringwood

Complete the following scope of work:

tem#	Feature	Method	Number	Cost Per unit	COST
		Enclose all exterior components of the exterior Jamb inTyvek wrap and coll metal stock for			
1	Exterior -Side D Door Jamb	clearance.	0)	\$0
2	Exterior- Side C- Side Door.	Remove and dispose of the Component. Replace with similar size,style and dimension.Prime and finish paint coat to all wood compnents.	0		\$0
3	Room -2-A- Door Jamb & Exterior side of door	Remove and dispose of the Component. Replace with similar size,style and dimension.Prime and finish paint coat to all wood compnents.	0		\$0
4	Room -1- B -A side Door Jamb	Enclose all exterior components of the exterior Jamb inTyvek wrap and coil metal stock for clearance.	О		\$0
5	0	0	0)	\$0
6	C	0	0		\$0
7	O	0	O		\$0
8	0	0	O		\$0
9		0	0		\$0
10	0	0	1		\$0
			total		\$0

8/8/2018

Contractors may submit an occupant protection plan on the form provided.

- ${\bf 1} \ \ {\bf Contact \ Lars \ Aamont \ if \ an \ additional \ form \ is \ needed. \ Phone \ 704-593-1640}$ Complete all interior work in a unit in a single day.
- 2 Allow for replacement of 50 board feet of rotted wood.
- 3 Unless otherwise noted any window or door removal and replacement
- 4 includes frame and trim on both sides. In lieu of complete removal, window frames may be enclosed with vinyl on
- 5 exterior in accordance with all project manual requirements
- 6 Contact Lars Aamont to conduct inspections prior to repainting or other putback and after vinyl siding installation.

Windows being placed in a bathroom need to be tempered glass.

	Total Bid P 2 #1C Acknowledgement of Adden	0	
	Addendum#		
			Date
Ì			
1	The undersigned contractor	agrees to perform the scope of work for the indica	ted
		cable regulations and the project manual. The at the work will be completed within 60 days of aw rector representative	
	Contractor Submitting Bid: Address: 950 Greater	1/25+tuais Builders LLi ext Falls +two SC 29706	C
	Phone: One Oaa	-U272	

803-899-4308

EXECUTIVE SUMMARY

The City of Charlotte contracted with The EI Group, Inc (EI) to conduct a lead-based paint inspection and risk assessment of the residences located at 2400 Ringwood Street, Charlotte, NC. The residence is a one-story multi-family duplex. Mr. Lars Aamoth performed the inspection and risk assessment on May 7, 2018. The scope of the survey included comprehensive XRF testing of interior and exterior painted surfaces, visual inspection, paint condition hazard ranking, dust wipe sampling, and soil sampling.

X-Ray Fluorescence (XRF) readings were collected in substantial conformance with industry standards and applicable federal and state regulations. Additionally, dust wipe samples and composite lead in soil samples were collected to identify potential lead-based paint hazards.

Painted surfaces that contain greater than or equal to 1.0 milligrams of lead per square centimeter (mg/cm²) are considered to be lead-based paint, as defined by the Department of Housing and Urban Development (HUD), the Environmental Protection Agency (EPA) and the North Carolina Health Hazards Control Unit (HHCU). Lead-based paint was found inside or outside of this residence.

The following is a summary of the survey findings for the subject property:

Interior Lead-Based Paint

- Room 1A B Side Door Jamb (Exterior Door)
- Room 2A C Side Door Jamb & Door (Exterior Door)
- Room 1B A Side Door Jamb (Exterior Door)

Exterior Lead-Based Paint

- Exterior B Side Fascia
- Exterior C Side Door
- Exterior D Side Door Jamb

Deteriorated Lead-Based Paint (Lead-Based Paint Hazards)

- Room 2A C Side Door Jamb & Door (Exterior Door)
- Exterior D Side Door Jamb
- Room 1B A Side Door Jamb (Exterior Door)

Lead in Dust Hazards

• None

Lead in Soil Hazards

None

This executive summary has been prepared for the convenience of the users of this report. This summary does not contain all the information presented in this report and, therefore, the entire report should be read to assure all pertinent information is transmitted.